Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: SMITH 34-12TFH CTB

Field Name: PARK Well File #:

Date Incident:3/13/2015Time Incident:12:08Facility ID Number:220526-01County:BILLINGSTwp:140Rng:100Sec:12Qtr:SW SE

Location Description:

Submitted By: Sarah Paycer Received By:

Contact Person: Sarah Paycer

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 6 barrels

Brine 6 Barrels 5 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/8/2015 Clean Up Concluded: 3/21/2015

Risk Evaluation:
None Noted

Areal Extent:

Potential Environmental Impacts:

None Noted

Action Taken or Planned:

Wells were shut in, a vac truck sucked out water from the leaking tank along with standing water in the berm. After the ONE call ticket clears (expected 3/18/2015), all impacted soil will be removed. In the future Whiting will continue to monitor tanks during freeze/thaw conditions.

Wastes Disposal Location: Chimney Butte Disposal

Agencies Involved:

Updates

Date: 3/16/2015 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.